



**No.127/FSR/RFO/Bng-South/2025**

**Dated: 01-12-2025**

To,  
Managing Trustee,  
M/s. Patel Ramaiah Educational & Cultural Trust(R),  
Kariyammana Agrahara,  
Behind Sakra World Hospital,  
Outer Ring Road, Bellandur Post,  
Bengaluru-560 103.

Sir,

Sub: Issue of '**Fire Advisory Certificate**' with respect to fire prevention, fire fighting and evacuation measures required to the Educational Building constructed and occupied at **M/s. Patel Ramaiah Educational & Cultural Trust (R)**, Kariyammana Agrahara, Behind Sakra World Hospital, Outer Ring Road, Bellandur Post, Bengaluru-560 103.

Ref: 1) Your request letter dated: 27-10-2025.  
2) Inspection report 77/DFO/SRFS/FSR/BNG/2025 Dt:24-11-2025.

With reference to the subject cited above, the District Fire Officer, Sarjapura Road Fire Station, Bengaluru was inspected the Educational building constructed & occupied at **M/s. Patel Ramaiah Educational & Cultural Trust (R)**, Kariyammana Agrahara, Behind Sakra World Hospital, Outer Ring Road, Bellandur Post, Bengaluru-560 103 on 31-10-2025 with respect to fire prevention, fire fighting and evacuation measures to be complied in the above premises and submitted the details as follows: -

**ANNEXURE-B**

***Group-A & B, FZ-1, Mixed Occupancy Building***

**A. Details of the building / premises :-**

01	Name and Address of the Applicant.	: Managing Trustee, M/s. Patel Ramaiah Educational & Cultural Trust(R), Kariyammana Agrahara, Behind Sakra World Hospital, Outer Ring Road, Bellandur Post, Bengaluru-560 103.
----	------------------------------------	---



02	Name and Address of the premises.	:	M/s. Patel Ramaiah Educational & Cultural Trust(R), Karriyammana Agrahara, Behind Sakra World Hospital, Outer Ring Road, Bellandur Post, Bengaluru-560 103.
03	Name and address of the Building owner	:	R.Sampath Kumar s/o A. Ramaiah Managing Trustee, M/s. Patel Ramaiah Educational & Cultural Trust(R), Karriyammana Agrahara, Behind Sakra World Hospital, Outer Ring Road, Bellandur Post, Bengaluru-560 103.
04	Number of buildings	:	One building
05	Number of floors	:	Lower Ground, Ground & 04 Upper floors.
06	Floor-wise details of occupancy:-		
	Lower Ground floor	:	05 Labs.
	Ground floor	:	04 Class Rooms & 01 Seminar Hall.
	1 <sup>st</sup> floor	:	09 Class Rooms, 01 Principal Cabin & 01 Library Room
	2 <sup>nd</sup> floor	:	10 Class Rooms, 01 Principal Cabin, 02 Staff Rooms & 01 Library Room.
	3 <sup>rd</sup> floor	:	07 Class Rooms, 01 Library, 01 Office Room & 01 Staff Room.
	4 <sup>th</sup> floor	:	29 Boarding Rooms.
07	Height of the building	:	20.00 Mtrs.
08	Site area	:	8,092.04 Sq. Mtrs.
09.	Built-up area of each floor:-		
	Lower Ground floor	:	1182.45 Sq. Mtrs.
	Ground floor	:	1182.45 Sq. Mtrs.
	1 <sup>st</sup> floor	:	1096.65 Sq. Mtrs.
	2 <sup>nd</sup> floor	:	1096.65 Sq. Mtrs.
	3 <sup>rd</sup> floor	:	1101.50 Sq. Mtrs.
	4 <sup>th</sup> floor	:	440.00 Sq. Mtrs.
10.	<b>Total built-up area</b>	:	<b>6,099.70 Sq. Mtrs.</b>
11.	Surrounding properties:-		
	East(Front)	:	08.00 mtrs wide road.
	West (Rear)	:	Vacant Land.
	North (Side)	:	Residential building.
	South (Side)	:	Vacant Land.
12.	<b>Set-back area available around the building :-</b>		
	East(Front)	:	01.60 Mtrs.
	West (Rear)	:	NIL.
	North (Side)	:	1.00 Mtrs.
	South (Side)	:	3.60 Mtrs.



**B. On inspection of this premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :-**

Sl. No. (1)	Details (02)	Existing (03)	Recommendations (04)																					
01.	Accessibility to the premises	The premises is accessible from 08.00 mtrs wide Road, located on Eastern side & connected to an 60.00 mtrs wide Outer ring road, located on Southern side. The road is hardened to carry the Weight of 45000 Kgs.	Complied.																					
02.	No. of entrances	01 entrance & 01 exit have been provided from 08.00 mtrs wide Road, located on Eastern side.	Complied.																					
03.	Width of entry / exit	01 entrance of 4.00 Mtrs width & 01 exit of 3.80 Mtrs width have been provided from 08.00 mtrs wide Road, located on Eastern side.	Complied.																					
04.	Diesel generators.	One Generator of 30 KVA capacity have been provided	Diesel Generator should be connected to emergency fire-fighting & lighting systems.																					
05.	No. of staircases available	<table border="1"> <tr> <td>Nos. of staircases</td> <td>:</td> <td>02 Nos.</td> </tr> <tr> <td>Width of staircases</td> <td>:</td> <td>1.20 Mtrs. 1.40 Mtrs.</td> </tr> <tr> <td>Width of treads</td> <td>:</td> <td>Each of 30 Cms.</td> </tr> <tr> <td>Height of risers</td> <td>:</td> <td>Each of 15 Cms</td> </tr> <tr> <td>Nos. of riser per flight</td> <td>:</td> <td>09 Nos.</td> </tr> <tr> <td>Height of handrails</td> <td>:</td> <td>Each of 1.00 Mtr.</td> </tr> <tr> <td>Head room clearance</td> <td>:</td> <td>Each of 2.20 Mtr.</td> </tr> </table>	Nos. of staircases	:	02 Nos.	Width of staircases	:	1.20 Mtrs. 1.40 Mtrs.	Width of treads	:	Each of 30 Cms.	Height of risers	:	Each of 15 Cms	Nos. of riser per flight	:	09 Nos.	Height of handrails	:	Each of 1.00 Mtr.	Head room clearance	:	Each of 2.20 Mtr.	Complied.
Nos. of staircases	:	02 Nos.																						
Width of staircases	:	1.20 Mtrs. 1.40 Mtrs.																						
Width of treads	:	Each of 30 Cms.																						
Height of risers	:	Each of 15 Cms																						
Nos. of riser per flight	:	09 Nos.																						
Height of handrails	:	Each of 1.00 Mtr.																						
Head room clearance	:	Each of 2.20 Mtr.																						
06.	No. lifts and capacity.	<table border="1"> <tr> <td>Nos. of lifts</td> <td>:</td> <td>01 no</td> </tr> <tr> <td>Capacity of lifts</td> <td>:</td> <td>06 Persons/ 408 Kgs</td> </tr> </table>	Nos. of lifts	:	01 no	Capacity of lifts	:	06 Persons/ 408 Kgs	Complied.															
Nos. of lifts	:	01 no																						
Capacity of lifts	:	06 Persons/ 408 Kgs																						
07.	Fire extinguisher	Not Provided.	Suitable Fire Extinguishers should be provided as																					



			<p>mentioned below.</p> <p>A. One ABC type extinguisher of 6Kgs capacity should be provided at each staircase landing.</p> <p>B. One CO2 type fire extinguisher of 4.5Kgs capacity should be provided near each electrical board, electrical room &amp; near Diesel Generator.</p> <p>C. One ABC type extinguisher of 6kgs capacity should be located as to be available within 15.00 m radius.</p>
08.	First aid Hose reel hose	Not Provided.	One Hose Reel hose of 19mm size of adequate length to reach the farthest point with a shut off branch having a nozzle of 5mm size near the staircase landing should be provided for every 1000 Sq. Mtrs area in each floor the building.
09.	Down Comer System	Not Provided.	01 Down comer system should be provided for every 1000 Sq. Mtrs area in each floor of the building. The system should be of 100 mm internal diameter and made of G.I. "C" class pipe. From each down comer single hydrant outlet has to be provided at each landing. Adequate B.I.S marked reinforced rubber lined 02 nos delivery hoses of 63mm size to reach the farthest point of the floor from the system with a branch pipe near each hydrant outlet should be provided.
10.	Manually operated electronic Fire alarm system.	Not provided.	Manually operated electrical fire alarm system with call points near the staircase



			should be provided in the building with its control panel at ground floor.
11.	Terrace tank over respective tower terrace.	Not Provided.	The down comer system should be connected to RCC Overhead tank of 25,000 ltrs capacity exclusively for firefighting.
12.	At the terrace tank level with minimum pressure of 3.5 kg/cm <sup>2</sup>	Not Provided.	The down comer system should be connected to one electrical driven pump capable of delivering 900LPM.
13.	Public address system	Not Provided.	Public Address system should be provided with its console at the control room, located on the ground floor of Building.
14.	Fire control room at ground floor.	Not provided.	Fire control room should be provided at ground floor with all its console at its control room panel.
15.	Escape routes	Not Displayed.	Escape routes should be marked visibly to guide the students /staffs to safer Places in case of emergency.
16.	Fire Siren	Not Provided.	A Fire siren should be installed inside the premises to inform all the inmates in case of a fire emergency and evacuate the area.
17.	No smoking board	Not Displayed.	No-Smoking board should be displayed in each floor.
18.	Nominate one fire Nodal Officer	Not Nominated.	One non-teaching staff has to be nominated as fire nodal officer for the premises.
19.	Fire order	Not Displayed.	Fire order board has to be displayed near each staircase of each floor with emergency telephone numbers of <b>Sarjapur-Road Fire Station i.e.080--25746166 &amp; 101</b> and telephone numbers of nearest Ambulance Service & Management.
20.	Fire fighting training	Not Trained.	40% of staff/employees Should be get trained in fire prevention And fire fighting



evacuation measures at R.A. Mundkur Fire & Emergency Services Academy, B.G.Road, Bengaluru-560 029.

**General Fire precautionary measures**

- a. The exit ways shall be kept clear always without any obstructions and the entire exit ways shall be marked with using illuminating paint.
- b. No fire in any form shall be used in the premises.
- c. Inflammables and explosive materials shall not be stored in the area.
- d. 'No Smoking' boards shall be displayed at appropriate places in the premises.
- e. If gangway shall be provided not less than 01.50mtrs between the record store box rows and wall. The rows space shall be always kept clear.
- f. The doors shall not be kept locked/ latched during working hours.
- g. Separate NOC has to be obtained from Department for the storage of Chemicals, Solvents, Petroleum products, LPG, etc in the premises/building.
- h. This Fire Safety Advisory Certificate is issued from the fire prevention, fire fighting and evacuation measures to the building. Karnataka State Fire & Emergency Services Department is not responsible for the ownership of the land, its location and other disputes, which may arise in due course.
- i. If any additional construction work is taken up in the building/premises without informed to the department, the Fire Advisory certificate deemed to be cancelled and necessary legal action will be initiated against the developer/management/tenant.

As such the Karnataka State Fire and Emergency Services department is issuing 'Fire Advisory Certificate' to the Educational building M/s. Patel Ramaiah Educational & Cultural Trust (R), Kariyammana Agrahara, Behind Sakra World Hospital, Outer Ring Road, Bellandur Post, Bengaluru-560 103. From Fire prevention, Fire fighting and Evacuation point of view subject to the compliance of below mentioned conditions within 03 months from the date of issue of Fire Advisory Certificate.

1. Diesel Generator should be connected to emergency fire-fighting & lighting systems.
2. Suitable Fire Extinguishers should be provided as mentioned below.
  - A. One ABC type extinguisher of 6Kgs capacity should be provided at each staircase landing.
  - B. One CO2 type fire extinguisher of 4.5Kgs capacity should be provided near each electrical board, electrical room & near Diesel Generator.
  - C. One ABC type extinguisher of 6kgs capacity should be located as to be available within 15.00 m radius.
3. One Hose Reel hose of 19mm size of adequate length to reach the farthest point with a shut off branch having a nozzle of 5mm size near the staircase landing should be provided for every 1000 Sq. Mtrs area in each floor the building.
4. 01 Down comer system should be provided for every 1000 Sq. Mtrs area in each floor of the building. The system should be of 100 mm internal diameter and made of G.I. "C" class pipe. From each down comer single hydrant outlet has to be provided at each landing. Adequate B.I.S marked reinforced rubber lined 02 nos delivery hoses of 63mm size to reach the farthest point of the floor from the system with a branch pipe near each hydrant outlet should be provided.



5. Manually operated electrical fire alarm system with call points near the staircase should be provided in the building with its control panel at ground floor.
6. The down comer system should be connected to RCC Overhead tank of 25,000 ltrs capacity exclusively for firefighting.
7. The down comer system should be connected to one electrical driven pump capable of delivering 900LPM.
8. Public Address system should be provided with its console at the control room, located on the ground floor of Building.
9. Fire control room should be provided at ground floor with all its console at its control room panel.
10. Escape routes should be marked visibly to guide the students /staffs to safer Places in case of emergency.
11. A Fire siren should be installed inside the premises to inform all the inmates in case of a fire emergency and evacuate the area.
12. No-Smoking board should be displayed in each floor.
13. One non-teaching staff has to be nominated as fire nodal officer for the premises.
14. Fire order board has to be displayed near each staircase of each floor with emergency telephone numbers of **Sarjapur-Road Fire Station i.e.080--25746166 & 101** and telephone numbers of nearest Ambulance Service & Management.
15. 40% of staff/employees Should be get trained in fire prevention And fire fighting evacuation measures at R.A. Mundkur Fire & Emergency Services Academy, B.G.Road, Bengaluru-560 029.

Note: -

1. This is only the "Fire Advisory certificate" issued by the Fire Department from fire safety view of the low-rise already constructed Building. This shall not be considered as No Objection Certificate for the Building.
2. After completion of all the fire fighting installations as advised in Fire Advisory Certificate, 'Fire Advisory Compliance Certificate' shall be obtained from the Fire and Emergency department.

  
**REGIONAL FIRE OFFICER** 1 <sup>12</sup>/<sub>25</sub>  
**Bengaluru South Range,**  
**Bengaluru - 560 029**

Copy to the DGP & DG, KSFES Bangalore.

-for your kind Information sir.

1) District Fire Officer, Sarjapura Road Fire Station,  
Bengaluru.



**No.269/CC/RFO/Bng-South/2025**

**Dated 09-12-2025**

ಗೆ,

Managing Trustee,

M/s Patel Ramaiah Educational & Clutural Trust(R),

Kariyammana Agrahara,

Behind Sakra World Hospital,

Outer Ring Road,

Bellandur Post,

Bengaluru-560 103.

ಮಾನ್ಯರೇ,

ವಿಷಯ : M/s Patel Ramaiah Educational & Clutural Trust(R), ಕರಿಯಮ್ಮನ ಅಗ್ರಹಾರ, ಸಕ್ರಾ ವರ್ಲ್ಡ್ ಆಸ್ಪತ್ರೆ ಹಿಂಬಾಗ, ಹೊರ ವರ್ತುಲ ರಸ್ತೆ, ಬೆಳ್ಳಂದೂರು ಪೋಸ್ಟ್, ಬೆಂಗಳೂರು-560 103. ಇಲ್ಲಿ ನಿರ್ಮಿಸಿರುವ ಕಟ್ಟಡಕ್ಕೆ ಸಮಾಪನ ಪತ್ರ ನೀಡುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ : 1) ಸಲಹಾ ಪತ್ರ ಸಂ. 127/FSR/RFO/Bng-South/2025 ದಿನಾಂಕ: 01-12-2025.  
2) ನಿಮ್ಮ ಪತ್ರ ದಿನಾಂಕ: 03-12-2025.

<<<<<<<>>>>>>>>

ಕರಿಯಮ್ಮನ ಅಗ್ರಹಾರ, ಸಕ್ರಾ ವರ್ಲ್ಡ್ ಆಸ್ಪತ್ರೆ ಹಿಂಬಾಗ, ಹೊರ ವರ್ತುಲ ರಸ್ತೆ, ಬೆಳ್ಳಂದೂರು ಪೋಸ್ಟ್, ಬೆಂಗಳೂರು-560 103. ಇಲ್ಲಿ ನಿರ್ಮಿಸಿರುವ 20.00 ಮೀಟರ್ ಎತ್ತರದ Lower Ground floor, Ground Floor & 4 Upper Floors ಹೊಂದಿರುವ ಕಟ್ಟಡ M/s Patel Ramaiah Educational & Clutural Trust(R), ಶೈಕ್ಷಣಿಕ ಕಟ್ಟಡಕ್ಕೆ ಅಗ್ನಿಶಾಮಕ ಮತ್ತು ತುರ್ತು ಸೇವಾ ಇಲಾಖೆಯಿಂದ ಈ ಮೇಲಿನ ಉಲ್ಲೇಖ (1) ರಂತೆ ದಿನಾಂಕ:01/12/2025 ರಂದು ನಿಮ್ಮ ಕೋರಿಕೆಯಂತೆ ಅಗ್ನಿಶಮನ ಸಲಹಾ ಪತ್ರ ನೀಡಲಾಗಿದೆ.

ಉಲ್ಲೇಖ (2) ರ ನಿಮ್ಮ ಪತ್ರದಲ್ಲಿ, ಸದರಿ ಶೈಕ್ಷಣಿಕ ಕಟ್ಟಡದಲ್ಲಿ ಅಗ್ನಿಶಮನ ಉಪಕರಣಗಳ ಅಳವಡಿಕೆ ಕಾರ್ಯ ಮುಗಿದಿದ್ದು, ಅಗ್ನಿಶಾಮಕ ಮತ್ತು ತುರ್ತು ಸೇವಾ ಇಲಾಖೆಯ ಸಮಾಪನ ಪತ್ರ ನೀಡುವಂತೆ ಕೋರಿರುವಿರಿ.

ನಿಮ್ಮ ಕೋರಿಕೆಯಂತೆ, ಜಿಲ್ಲಾ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿ, ಸರ್ಜಾಪುರ ರಸ್ತೆ ಅಗ್ನಿಶಾಮಕ ತಾಣ, ಕರ್ನಾಟಕ ಅಗ್ನಿಶಾಮಕ ಮತ್ತು ತುರ್ತು ಸೇವೆಗಳು ರವರು ದಿನಾಂಕ: 09/12/2025 ರಂದು ಕರಿಯಮ್ಮನ ಅಗ್ರಹಾರ, ಸಕ್ರಾ ವರ್ಲ್ಡ್ ಆಸ್ಪತ್ರೆ ಹಿಂಬಾಗ, ಹೊರ ವರ್ತುಲ ರಸ್ತೆ, ಬೆಳ್ಳಂದೂರು ಪೋಸ್ಟ್, ಬೆಂಗಳೂರು-560 103 ಇಲ್ಲಿ ನಿರ್ಮಿಸಿರುವ ಶೈಕ್ಷಣಿಕ ಕಟ್ಟಡವನ್ನು ಪರಿವೀಕ್ಷಣೆ ಮಾಡಿ ಅಗ್ನಿಶಾಮಕ ಮತ್ತು ತುರ್ತು ಸೇವಾ ಇಲಾಖೆಯು ನೀಡಿರುವ ಸಲಹಾ ಪತ್ರದಂತೆ, ಅಗ್ನಿರಕ್ಷಣೆ ಮತ್ತು ನಿಯಂತ್ರಣ, ಅಗ್ನಿ ನಂದಿಸುವ ಉಪಕರಣಗಳ ಅಳವಡಿಕೆ ಹಾಗೂ




ರಕ್ಷಣಾ ಕ್ರಮಗಳನ್ನು ಶೈಕ್ಷಣಿಕ ಕಟ್ಟಡದಲ್ಲಿ ಪೂರ್ಣವಾಗಿ ಅನುಷ್ಠಾನಗೊಳಿಸಿರುವುದಾಗಿ ಹಾಗೂ ಸದರಿ ಕಟ್ಟಡದಲ್ಲಿನ ನೌಕರರು/ಸಿಬ್ಬಂದಿಗಳಿಗೆ ಅಗ್ನಿಶಮನ ಕುರಿತ ತರಬೇತಿ ಮಾತ್ರ ಬಾಕಿ ಇರುವುದಾಗಿ ಹಾಗೂ ಸದರಿ ಕಟ್ಟಡದ ಸಮಾಪನ ಪತ್ರ ತರುವಾಯ ಅದರಲ್ಲಿನ ಸಿಬ್ಬಂದಿಗಳಿಗೆ ಅಗ್ನಿಶಮನ ಕುರಿತು ತರಬೇತಿ ವ್ಯವಸ್ಥಿಸಲು ಸಾಧ್ಯವಾಗುತ್ತದೆಂದು ತಿಳಿಸಿರುತ್ತಾರೆ.

ಆದ್ದರಿಂದ ಕರಿಯಮ್ಮನ ಅಗ್ರಹಾರ, ಸಕ್ರಾ ವರ್ಲ್ಡ್ ಆಸ್ಪತ್ರೆ ಹಿಂಬಾಗ, ಹೊರ ವರ್ತುಲ ರಸ್ತೆ, ಬೆಳ್ಳೊಂದೂರು ಪೋಸ್ಟ್, ಬೆಂಗಳೂರು-560 103. ಇಲ್ಲಿ ನಿರ್ಮಿಸಿರುವ 20.00 ಮೀಟರ್ ಎತ್ತರದ Lower Ground floor, Ground Floor & 4 Upper Floors ಹೊಂದಿರುವ ಕಟ್ಟಡ M/s Patel Ramaiah Educational & Clutural Trust(R), ಶೈಕ್ಷಣಿಕ ಕಟ್ಟಡಕ್ಕೆ ಅಗ್ನಿಶಾಮಕ ಮತ್ತು ತುರ್ತು ಸೇವಾ ಇಲಾಖೆಯ ಸಲಹಾ ಪತ್ರ ಸಂ. 127/FSR/RFO/Bng-South/2025 ದಿನಾಂಕ: 01-12-2025 ರಲ್ಲಿ ತಿಳಿಸಿರುವಂತೆ, ಅಗ್ನಿರಕ್ಷಣೆ ಮತ್ತು ನಿಯಂತ್ರಣ ಹಾಗೂ ಅಗ್ನಿ ನಂದಿಸುವ ಉಪಕರಣಗಳ ಅಳವಡಿಕೆ ಹಾಗೂ ರಕ್ಷಣಾ ಕ್ರಮಗಳನ್ನು ಕಟ್ಟುನಿಟ್ಟಾಗಿ ಪಾಲಿಸಬೇಕೆಂದು ಹಾಗೂ ನಿಮ್ಮ ದಿನಾಂಕ: 09/12/2025 ರ ಮುಚ್ಚಳಿಕೆ ಪತ್ರದಲ್ಲಿ ಒಪ್ಪಿರುವಂತೆ, ಅಗ್ನಿಶಮನ ಉಪಕರಣಗಳನ್ನು ಸುಸ್ಥಿತಿಯಲ್ಲಿಡಬೇಕೆಂಬ ಹಾಗೂ ಕಟ್ಟಡದಲ್ಲಿನ ಶೇಕಡಾ 40% ರಷ್ಟು ಸಿಬ್ಬಂದಿ/ನೌಕರರಿಗೆ ಅಗ್ನಿರಕ್ಷಣೆ ಮತ್ತು ನಿಯಂತ್ರಣ ಕ್ರಮಗಳ ಬಗ್ಗೆ ಬೆಂಗಳೂರಿನ ಆರ್. ಎ. ಮುಂಡ್ಕೂರ್ ಅಗ್ನಿಶಾಮಕ ಮತ್ತು ತುರ್ತು ಸೇವೆಗಳ ಅಕಾಡೆಮಿಯಲ್ಲಿ ಸೂಕ್ತ ತರಬೇತಿಯನ್ನು 03 ತಿಂಗಳೊಳಗೆ ಪಡೆಯಲು ವ್ಯವಸ್ಥಿಸಬೇಕೆಂಬ ಷರತ್ತಿನ ಮೇಲೆ ಸಮಾಪನ ಪತ್ರವನ್ನು ಅಗ್ನಿಶಾಮಕ ಮತ್ತು ತುರ್ತು ಇಲಾಖೆಯಿಂದ ನೀಡಲಾಗಿದೆ.

ಈ ಸಮಾಪನ ಪ್ರಮಾಣ ಪತ್ರವು ದಿನಾಂಕ:-30-11-2027 ರವರೆಗೆ ಚಾಲ್ತಿಯಲ್ಲಿರುತ್ತದೆ. ತದನಂತರ ಈ ಸಮಾಪನ ಪತ್ರವನ್ನು ನವೀಕರಿಸುವಂತೆ ತಿಳಿಸಲಾಗಿದೆ.

ಹಾಗೆಯೇ ಒಂದು ವೇಳೆ ಯಾವುದೇ ಸಂದರ್ಭದಲ್ಲಿ ಇಲಾಖೆಯ ಶಿಪಾರಸ್ಸಿನನ್ವಯ ಅಳವಡಿಸಿರುವ ಅಗ್ನಿನಿವಾರಣೆ ಹಾಗೂ ಅಗ್ನಿಶಮನ ಉಪಕರಣಗಳು ಸುಸ್ಥಿಯಲ್ಲಿರದೇ ಇರುವುದು ಕಂಡು ಬಂದರೆ ಅಥವಾ ರಕ್ಷಣಾ ಕ್ರಮಗಳನ್ನು ಕಟ್ಟುನಿಟ್ಟಾಗಿ ಪಾಲಿಸದಿದ್ದರೆ ಅಥವಾ ಕಾನೂನಿನನ್ವಯ ಸದರಿ ಕಟ್ಟಡದ ಸುತ್ತ ಬಿಟ್ಟಿರುವ ತೆರೆದ ಪ್ರದೇಶದಲ್ಲಿ ಯಾವುದೇ ಹೆಚ್ಚುವರಿ ರಚನೆಗಳನ್ನು ನಿರ್ಮಾಣ ಮಾಡಿದರೆ ಅಥವಾ ಯಾವುದೇ ರೀತಿಯ ಖಾಯಂ/ತಾತ್ಕಾಲಿಕ ಅಡಚಣೆಗಳನ್ನು ಉಂಟು ಮಾಡಿದರೆ, ಈ ಸಮಾಪನ ಪತ್ರವು ಅನೂರ್ಜಿತಗೊಳ್ಳುವುದು ಹಾಗೂ ಕಾನೂನಿನ ಚೌಕಟ್ಟಿನಲ್ಲಿ ಮುಂದಿನ ಕ್ರಮ ಕೈಗೊಳ್ಳಲಾಗುವುದು ಎಂಬುದಾಗಿ ಸೂಚಿಸಲಾಗಿದೆ.

  
ಪ್ರಾದೇಶಿಕ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿ <sup>Kr 9/12/25</sup>  
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ವಲಯ  
ಬನ್ನೇರುಘಟ್ಟ ರಸ್ತೆ, ಬೆಂಗಳೂರು-29

- 1) ಪ್ರತಿಯನ್ನು ಗೌರವಗಳೊಂದಿಗೆ,  
ಮಾನ್ಯ ಪೋಲೀಸ್ ಮಹಾ ನಿರ್ದೇಶಕರು ಹಾಗೂ ಮಹಾ ನಿರ್ದೇಶಕರು,  
ಕರ್ನಾಟಕ ರಾಜ್ಯ ಅಗ್ನಿಶಾಮಕ ಮತ್ತು ತುರ್ತು ಸೇವೆಗಳು.
- 2) ಜಿಲ್ಲಾ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿ,  
ಸರ್ಜಾಪುರ ರಸ್ತೆ ಅಗ್ನಿಶಾಮಕ ಠಾಣೆ.